

## 1.4.2 INDICATIVE PROJECT COSTS McCosh Hall

## PROPOSED WORKS

## Prices include contingency @10% and VAT @ 20%

## A Repair works

.1	External wall repairs lime repointing, stitching cracks, steel, stone indents, chimney repairs £20,000 plus contingency and VAT	£26,400
.2	Roof	
	re- slating, leadwork, timber treatment £23,000 plus contingency and VAT	£30,360
.3	Rainwater goods	
	replace corroded cast iron, de-rust and redecorate £6,000 plus contingency and VAT	£7,920
.4	Windows	
	repair and redecorate 17 windows, replace 7 no windows £22,700 plus contingency and VAT	£29,964
.5	Boundary walls	
	part re-build, lime repointing £4,050 plus contingency and VAT	£5,346
SUB-TOTAL REPAIR ITEMS incl. contingency and VAT		£99,990